

PRINTED: 06/06/2013
FORM APPROVED

Division of Health Care Facilities

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER: TN1929	(X2) MULTIPLE CONSTRUCTION A. BUILDING: 01 - MAIN BUILDING 01 B. WING _____	(X3) DATE SURVEY COMPLETED R 05/30/2013
NAME OF PROVIDER OR SUPPLIER VANCO MANOR NURSING AND REHABILITATION		STREET ADDRESS, CITY, STATE, ZIP CODE 813 S DICKERSON RD GOODLETTSVILLE, TN 37072		
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)	(X5) COMPLETE DATE
N 848	<p>1200-8-6-.08 (18) Building Standards</p> <p>(18) It shall be demonstrated through the submission of plans and specifications that in each nursing home a negative air pressure shall be maintained in the soiled utility area, toilet room, janitor's closet, dishwashing and other such soiled spaces, and a positive air pressure shall be maintained in all clean areas including, but not limited to, clean linen rooms and clean utility rooms.</p> <p>This Rule is not met as evidenced by: Based on observation and testing, it was determined the facility failed to maintain the negative pressure.</p> <p>The finding included:</p> <p>Observation and testing of the laundry on 5/30/13 at 9:00 AM, revealed positive air pressure in the dirty laundry.</p> <p>This finding was verified by the maintenance director and acknowledged by the administrator during the exit conference on 5/30/13.</p>	N 848	<p><u>Corrective Action:</u></p> <ol style="list-style-type: none"> 1) Facility installed a new fire rated door between clean and soiled laundry rooms in order to ensure the negative pressure is maintained between the clean laundry room and the soiled laundry room. Installation completed on 4/26/13 2) Maintenance Director cleaned exhaust fan where it was clogged up. Maintenance Director redirected air flow to ensure the negative pressure is maintained between the clean laundry room. 5/31/13 3) Laundry department staff was in-serviced by Administrator 6/14/13 regarding Life Safety Code K067; keeping the laundry door closed between the clean laundry and soiled laundry room to maintain negative air flow pressure. 4) Maintenance Director will create and maintain a daily monitor log and ensure the door between the soiled laundry room and the clean laundry room maintains a negative pressure. The negative pressure log will be reviewed quarterly through the quality assurance program to ensure the deficient practice does not recur. <p>Completion Date: 6/14/13</p>	

Division of Health Care Facilities

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

STATE FORM

0699

VETJ22

TITLE

(X6) DATE

If continuation sheet 1 of 1